
EXECUTIVE SUMMARY REPORT

ADDITIONS & REMODELING TO: KROMREY MIDDLE SCHOOL

06/05/2015

What's New?

Work on MEP rough-ins is complete inside as well as painting in the gym. Over the next couple weeks lights and gym equipment will be installed in preparation for flooring. Outside, grading is progressing and crews have begun site work on the north side of the building.

The Past Weeks

- MEP rough-ins
- Interior painting
- Final grading of the site

Coming Up in the Weeks Ahead

- Install gym equipment
- Casework installation
- Continue site work



Retaining walls being put in along the Fieldhouse



Acoustical wall panels installed in the Fieldhouse



The new athletic field is ready for topsoil to be spread.



Did you know? During the final phase of the project an additional 61 parking spots will be added. This will add more parking on both the north and east sides of the building.