

# EXECUTIVE SUMMARY REPORT

## ADDITIONS & REMODLEING TO: KROMREY MIDDLE SCHOOL

06/06/14

### What's New?

Tours were provided for future 5<sup>th</sup> graders from Elm Lawn, Northside, and Sauk Trail elementary schools this week. The students visited Kromrey to see the new 5<sup>th</sup> grade wing and cafeteria this week, and were very excited to see the finishes progressing for phase I of the project. Terrazzo floors have been completed in the cafeteria and main corridors, and vinyl floor installation has begun in 5<sup>th</sup> grade classrooms. Acoustical panels, bathroom tiling and plumbing fixtures are being installed in the main entrance and main bathrooms. Drywall installation, taping and painting is continuing in the 6<sup>th</sup>, 7<sup>th</sup> and 8<sup>th</sup> grade wing in preparation for the next delivery of casework and lockers.

### The Past Weeks


- Completion of terrazzo floors – Area C
- Installation of the stage floor has begun – Area C
- Bathroom tiling and plumbing fixture installation – Area C
- Installation of 5<sup>th</sup> grade classroom vinyl flooring – Area D
- Painting in the east portion of the 6<sup>th</sup> grade wing – Area B
- Drywall installation in the west portion of the 7<sup>th</sup> grade wing – Area A
- Installation of 5<sup>th</sup> grade stairs – Area D
- Site staking and grading – Site

### Coming Up in the Weeks Ahead

- Drywall installation in the west portion of the 6<sup>th</sup> grade wing – Area A
- Painting in the east portion of the 6<sup>th</sup> grade wing – Area B
- Locker installation in the east portion of the 6<sup>th</sup>, 7<sup>th</sup> and 8<sup>th</sup> grade wing – Area B
- Casework installation in the east portion of the 6<sup>th</sup> grade wing – Area B
- Pouring front entrance sidewalks – Site
- Amphitheater Landscaping – Site



Future 5<sup>th</sup> grade students from Elm Lawn, Northside and Sauk Trail visited Kromrey for tours of the 5<sup>th</sup> grade wing



Sound absorbing wall panels, lights, and various other finishes are being installed in the main entrance and corridors – Area C



Vinyl floor tile is being installed in 5<sup>th</sup> grade classrooms – Area D



Grading at the front entrance is being completed in preparation for sidewalks. - Site



Plumbing fixtures and wall tile are being installed in the main bathrooms – Area C



**Did you know?** Studies have found that classroom acoustics are directly correlated to student learning and comprehension. Kromrey Middle School has many acoustical features that will help prevent noise from resonating throughout the school. These features include acoustical ceiling insulation in the band room and main entrance, sound reflecting ceiling panels in the band room, sound absorbing ceiling clouds above the stage, and sound absorbing wall panels in the corridors.