
EXECUTIVE SUMMARY REPORT

ADDITIONS & REMODELING TO: KROMREY MIDDLE SCHOOL

1/31/2014

What's New?

The structure of the 6th, 7th & 8th grade wing is nearing completion. Ironworkers are finishing the roof and closing in the courtyard. On the exterior of the building, masonry is being installed and work continues on the cafeteria roof. Inside, drywall has been installed on the walls in the 5th grade wing.



Geothermal well drilling continues in what will become the new parking lot.

The Past Week

- 6th, 7th & 8th grade wing structural steel
- Drilling geothermal wells
- Slab on grade in the cafeteria
- 5th grade wing drywall installation
- Exterior masonry



Drywall is on the walls in the 5th grade classroom. In the next couple weeks the rooms will receive paint.

Coming Up in the Weeks Ahead

- Finish 6th, 7th & 8th grade wing structural steel
- Finish roofing at cafeteria
- Drilling geothermal wells
- Exterior masonry
- Drywall taping and painting in the 5th grade wing



Inside the cafeteria, masons are laying block for the interior walls.



Workers place concrete in the new band room.



Did you know? Steel is one of the most recycled materials in the world. The average steel beam contains 88% recycled material making steel a very green building material!