

---

# EXECUTIVE SUMMARY REPORT

## ADDITIONS & REMODLEING TO: KROMREY MIDDLE SCHOOL

1/3/2014

---

### What's New?

Crews have been working through the cold weather onsite. Outside work continues on the three story structure and geothermal well borings. Inside contractors are installing mechanical, electrical and plumbing rough-ins in the cafeteria and 5<sup>th</sup> grade wing. Preparations are also underway in the cafeteria for the concrete slabs and interior masonry walls.

### The Past Week

- 6<sup>th</sup>, 7<sup>th</sup> & 8<sup>th</sup> grade wing structural steel
- Timber beam installation in the library
- Mechanical rough-ins in the 5<sup>th</sup> grade wing & cafeteria
- Drilling geothermal wells

### Coming Up in the Weeks Ahead

- 6<sup>th</sup>, 7<sup>th</sup> & 8<sup>th</sup> grade wing structural steel
- Mechanical and electrical rough-ins in the cafeteria
- Timber roof installation in the library
- Roofing at the cafeteria
- Drilling geothermal wells
- 2<sup>nd</sup> floor concrete slab pour



Wall framing on the three story wing is underway.



The first drill rig is onsite and boring geothermal wells.



The cafeteria has been enclosed and contractors are preparing for the concrete slabs.



Wall framing is complete in the 5<sup>th</sup> grade wing and subcontractors are installing mechanical and electrical systems in the walls.



**Did you know?** The stone used on the exterior of the building is quarried right here in Wisconsin. The material is produced by Valders stone based in Valders Wisconsin.